

Summary of Facility Information in the County of Wheatland

Owner Name and Address: S & W Station LLC 1918 Edgewood Dr Billings MT 59102 Phone: (406) 252-4661

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-----------------|-------------------------|---------------|-------|----------------|
| 5404934 | Engineers Depot | 102 2nd N E | Harlowton | 59036 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|-----------------------|-------------------|--|-------------------------------------|-------------|--|-------------------------|
| 5 / 05 Currently in Use | 1045 | 11/17/1988 17 / No | Gasoline 4,000 | STI-P3 None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Currently in Use | 1046 | 11/17/1988 17 / No | Gasoline 4,000 | STI-P3 None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 7 / 07 Currently in Use | 4342 | 11/17/1988 17 / No | Gasoline 4,000 | STI-P3 None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 8 / 08 Currently in Use | 4850 | 7/17/2003 02 / No | Diesel 6,000 | STI-P3 None | Flexible Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 5409085 | Malmstrom AFB K 1 | US Highway 12 | Harlowton | 59036 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|--------------|----------------------|---------------------|---|-------------------------------------|--------------|---|-------------------------|
| 3 / 03 Currently in Use | 341 | 5/2/1962 44 / No | Diesel 12,000 | Cathodically Protected Steel Lined Interior/Impressed Curr | Flexible Plastic Double-Walled | U.S. Suction | <div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B) (D) (E) (F) (G) (H) (I) (J) (K) (L) </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 5409086 | Malmstrom AFB K 2 | US Highway 191 | Harlowton | 59036 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|------------------|--|--|--------------|---|-------------------------|
| 1 / 02 Currently in Use | 342 | 6/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div style="display: flex; justify-content: space-between; padding: 2px;"> (A)(B)(C)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------|-------------------------|---------------|-------|----------------|
| 5409087 | Malmstrom AFB K 3 | US Highway 191 | Harlowton | 59036 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|--------------|----------------------|---------------------|--|--|--------------|--|-------------------------|
| 2 / 02 Currently in Use | 343 | 6/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 5409088 | Malmstrom AFB K 4 | US Highway 12 | Harlowton | 59036 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|--------------|----------------------|---------------------|--|--|--------------|---|-------------------------|
| 2 / 02 Currently in Use | 344 | 6/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (●) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B) (D) (E) (F) (●) (H) (I) (J) (K) (L) </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 5409090 | Malmstrom AFB K 6 | US Highway 12 | Harlowton | 59036 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|--------------|----------------------|---------------------|--|--|--------------|---|-------------------------|
| 2 / 02 Currently in Use | 346 | 6/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div style="display: flex; justify-content: space-between; padding: 2px;"> (A)(B)(C)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 5409092 | Malmstrom AFB K 8 | US Highway 191 | Harlowton | 59036 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|--------------|----------------------|---------------------|--|--|--------------|---|-------------------------|
| 1 / 02 Currently in Use | 348 | 6/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div style="display: flex; justify-content: space-between; padding: 2px;"> (A)(B)(C)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 5409093 | Malmstrom AFB K 9 | US Highway 12 | Harlowton | 59036 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|--------------|----------------------|---------------------|--|--|--------------|---|-------------------------|
| 2 / 02 Currently in Use | 349 | 6/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div style="display: flex; justify-content: space-between; padding: 2px;"> (A)(B)(C)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 5409094 | Malmstrom AFB K 10 | US Highway 12 | Harlowton | 59036 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|--------------|----------------------|---------------------|--|--|--------------|---|-------------------------|
| 2 / 02 Currently in Use | 350 | 6/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div style="display: flex; justify-content: space-between; padding: 2px;"> (A)(B)(C)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 5409095 | Malmstrom AFB K 11 | US Highway 12 | Harlowton | 59036 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|--------------|----------------------|---------------------|--|--|--------------|---|-------------------------|
| 2 / 02 Currently in Use | 351 | 6/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div style="display: flex; justify-content: space-between; padding: 2px;"> (A)(B)(C)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B)(D)(E)(F)(●)(H)(I)(J)(K)(L) </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: Thomas C Bennett PO Box 749 Harlowton MT 59036 Phone: (406) 632-4533

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-----------------|-------------------------|---------------|-------|----------------|
| 5409676 | Wades Drive Inn | US Highway 191 | Harlowton | 59036 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|----------------------------------|-----------|----------------------|---------------------|--|--|-------------|--|-------------------------|
| 2 / S2 Temporarily Out of Use | 432 | 1/5/1988 18 / Ye | Gasoline 8,000 | Unknown None | Galvanized Steel Cathodically Protected | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B ● E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / S3 Temporarily Out of Use | 433 | 1/5/1988 18 / Ye | Gasoline 8,000 | Unknown None | Galvanized Steel Cathodically Protected | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B ● E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: Ray & Alma Hinand Trust PO Box 306 Harlowton MT 59036 Phone: (406) 632-4329

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------------|-------------------------|---------------|-------|----------------|
| 5411975 | Rays Sport & Western Wear | US Highway 12 E | Harlowton | 59036 | (406) 632-4329 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|-------------------|---|---------------------------------------|-------------|---|-------------------------|
| 1 / 01 Currently in Use | 2362 | 5/1/1984 22 / No | Diesel 8,000 | Asphalt Coated or Bare Steel Impressed Current | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 02 Currently in Use | 2363 | 5/1/1984 22 / No | Gasoline 8,000 | Asphalt Coated or Bare Steel Impressed Current | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 03 Currently in Use | 2364 | 1/1/1984 22 / No | Gasoline 8,000 | Asphalt Coated or Bare Steel Impressed Current | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------|-------------------------|---------------|-------|----------------|
| 1409096 | Malmstrom AFB L 1 | US Highway 191 | Judith Gap | 59453 | |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|----------------------------|-----------|---------------------|------------------|---|-----------------------------------|--------------|--|--|--------------------|
| Status | | | | | | | | | Spill/Overl/C |
| 1 / 01 Currently in Use | 186 | 5/2/1962 44 / No | Diesel 12,000 | Cathodically Protected Steel Lined Interior/Impressed Curr | Flexible Plastic Double-Walled | U.S. Suction | <div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B D <input checked="" type="radio"/> F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div> | <div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div>B D <input checked="" type="radio"/> F <input checked="" type="radio"/> H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: David Miller 302 High St PO Box 228 Judith Gap MT 59453 Phone: (406) 473-2321

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|----------------|-------------------------|---------------|-------|----------------|
| 5407616 | Judith Gap Oil | 302 High St | Judith Gap | 59453 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|-----------------------|---------------------|--|---|--------------|--|-------------------------|
| 5 / 05 Currently in Use | 1621 | 12/28/1989 16 / No | Diesel 6,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Currently in Use | 1622 | 12/28/1989 16 / No | Gasoline 6,000 | STI-P3 None | Fiberglass Reinforced Plastic Cathodically Protected | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------|-------------------------|---------------|-------|----------------|
| 5409098 | Malmstrom AFB L 3 | Road 297 | Judith Gap | 59453 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|--------------|----------------------|---------------------|--|--|--------------|--|-------------------------|
| 2 / 02 Currently in Use | 352 | 6/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------|-------------------------|---------------|-------|----------------|
| 5409099 | Malmstrom AFB L 4 | Road 297 | Judith Gap | 59453 | |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|----------------------------|-----------|----------------------|------------------|--|--|--------------|--|--|--------------------|
| 2 / 02 Currently in Use | 353 | 6/10/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------|-------------------------|---------------|-------|----------------|
| 5409100 | Malmstrom AFB L 5 | Road 297 | Judith Gap | 59453 | |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|----------------------------|-----------|---------------------|------------------|--|--|--------------|--|--|--------------------|
| 2 / 02 Currently in Use | 354 | 6/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------|-------------------------|---------------|-------|----------------|
| 5409101 | Malmstrom AFB L 6 | Road 297 | Judith Gap | 59453 | |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|----------------------------|-----------|----------------------|------------------|--|--|--------------|--|--|--------------------|
| 2 / 02 Currently in Use | 355 | 3/26/1990 16 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------|-------------------------|---------------|-------|----------------|
| 5409102 | Malmstrom AFB L 7 | US Highway 191 | Judith Gap | 59453 | |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|----------------------------|-----------|---------------------|------------------|--|--|--------------|--|--|--------------------|
| 2 / 02 Currently in Use | 356 | 5/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------|-------------------------|---------------|-------|----------------|
| 5409103 | Malmstrom AFB L 8 | US Highway 191 | Judith Gap | 59453 | |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|----------------------------|-----------|---------------------|------------------|--|--|--------------|--|--|--------------------|
| 2 / 02 Currently in Use | 357 | 5/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------|-------------------------|---------------|-------|----------------|
| 5409089 | Malmstrom AFB K 5 | US Highway 12 | Shawmut | 59078 | |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|----------------------------|-----------|---------------------|------------------|--|--|--------------|--|--|--------------------|
| 2 / 02 Currently in Use | 345 | 6/9/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | <div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Wheatland

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 5409091 | Malmstrom AFB K 7 | US Highway 12 | Shawmut | 59078 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|--------------|----------------------|---------------------|--|--|--------------|---|-------------------------|
| 2 / 02 Currently in Use | 347 | 6/1/1993 13 / No | Diesel 4,000 | Fiberglass Reinforced Plastic Double-Walled | Fiberglass Reinforced Plastic Double-Walled | U.S. Suction | <div style="display: flex; justify-content: space-between; padding: 2px;"> (A) (B) (C) (D) (E) (F) (●) (H) (I) (J) (K) (L) </div> <div style="display: flex; justify-content: space-between; padding: 2px;"> (B) (D) (E) (F) (●) (H) (I) (J) (K) (L) </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |